

Technical *data*

Change of the tension pulley in the kit CT 1045 K1 for Renault 1.2 16 V

Defect pattern:

The barrel jacket material of the tension pulley in the kit is different from that of the removed pulley.

Cause:

The barrel jacket of the tension pulley was changed by the manufacturer from sintered metal to plastic.

Measure:

The new pulley can be used without limitations.

