

## SWAG 10 92 1174

to fit:  
Various Mercedes-Benz models

SWAG®



EN

## Rubber Metal Bush for Wheel Bearing Housing

### Problem

Knocking or creaking noises may be heard from the rear axle area while driving.

### Cause

The original design of this bush is very susceptible to wear. This stems from insufficient internal lubrication. Wear is accelerated when the vehicle is driven in harsh road and weather conditions.

### Solution

SWAG 10 92 1174 has been improved. The modified bush has several channels instead of just one. This ensures a permanent supply of lubricant which lengthens the bush's service life.

For more technical information please visit: [partsfinder.bilsteingroup.com](https://partsfinder.bilsteingroup.com)