



## SERVICE INFO – INA 0092



# Optičke razlike klackalica ventila Kat.Br. 422 0053 10

Modeli:	
Audi:	A1, A3
Seat:	Altea, Ibiza, Leon
Skoda:	Fabia, Octavia, Superb
VW:	Eos, Golf IV, Golf Plus, Golf V, Golf VI, Jetta III, Passat (C3_), Polo (6R_), Polo (9N_)
Motori:	1.4 FSI, 1.4 TSI, 1.4 TFSI, 1.6 16V, 1.6 FSI
OE brojevi:	422 0053 10
OE brojevi:	036 109 411 E 036 1 09 411 G 036 109 411 H 036 109 411 J



Slika 1: Izvedba 1

Prilikom zamjene klackalica ventila Kat.Br. 422 0053 10, moguće je pronaći ugrađene na vozilu oba dvije izvedbe prikazane na slikama 1 i 2.

Schaeffler Automotive Aftermarket dobavlja izvedbu klackalice ventila prikazanu na Slici 1.

### Uvijek zamjenjujte klackalice ventila u setu!

U slučaju kvara na jednoj ili više klackalica ventila, neizostavno je promjeniti sve klackalice ventila. Da bi se izbjegli višestruki popravci i povećani troškovi, uvijek istovremeno zamijenite; klackalica ventila i element za podešavanje zazora ventila za vrijeme servisnog zahvata.



Slika 2: Izvedba 2

Pridržavajte se uputa proizvođača vozila!

Odgovarajući rezervni dijelovi i tehničke informacije mogu se pronaći na [www.schaeffler-aftermarket.com](http://www.schaeffler-aftermarket.com) ili na [www.RepXpert.com](http://www.RepXpert.com).

### Za daljnje informacije:

Phone: +44 (0) 14 32 264 264\*

Fax: +44 (0) 14 32 375 760

Info@LuK-AS.co.uk

[www.schaeffler-aftermarket.com](http://www.schaeffler-aftermarket.com)

**SCHAEFFLER**  
AUTOMOTIVE AFTERMARKET



INA 0092