



## INA Service Info



# Tensioner pulley 531 0851 10

## Modified specifications

Manufacturer: Audi, Seat, Skoda, VW

### Models:

Audi: A3, A4, A6, TT  
 Seat: Altea, Leon, Toledo  
 Skoda: Octavia  
 VW: EOS, Golf, Golf Plus, Jetta, Passat, Touran

Engines: 2.0 FSI, 2.0 TFSI, 2.0 RS

Part no.: 531 0777 10 (replaced)  
 531 0851 10 (new)  
 530 0445 09 (Set)  
 530 0445 10 (KIT)  
 530 0445 31 (KIT + waterpump)  
 530 0584 09 (Set)  
 530 0584 10 (KIT)

OE number: 06D 109 243 B (replaced)  
 06D 109 243 C (new)




Photo 1: 531 0777 10 – Old tensioner pulley (979743)



Photo 2: 531 0851 10 – New tensioner pulley (979830)

Due to modified specifications, the tensioner pulley 531 0851 10 replaces tensioner pulley 531 0777 10.

The new tensioner pulley is also replaced in Set 530 0445 09, KIT 530 0445 10 and water pump KIT 530 0445 31.

The only visual difference between the two tensioners pulleys is the number stamped on their rear face (fig. 1 and fig. 2).

Installation of the tensioner pulley with the number 979743 in place of the tensioner pulley with the number 979830 is not permitted.

Please observe the vehicle manufacturer specifications!

**You want more? We can help!**

Phone: +44 (0) 1432 264 264  
 Fax: +44 (0) 1432 375 760  
 aftermarket.uk@schaeffler.com  
 www.repxpert.co.uk