



# VKBA 3526

## Technická informace

VKBA 3526



Přední náprava: C70 I, S70, V70 I



### Návod k montáži hnací hřídele při výměně ložiska kola



Ložisko kola a všechny související součásti jsou při jízdě vozu vystaveny různým silám a šilným nárazům. Aby byla hnací hřídel vždy dostatečně tuhá, je nutno VZDY nanést lepidlo na drážky hřídele. Tím se vymezení vůle a odstraní se hluk a vibrace nebo předčasné selhání ložiska.

### Instrukce k montáži

- Před montáží vždy řádně očistěte drážky
- Na očištěné plochy naneste 3 - 4 mm silnou vrstvu lepidla
- Po nanesení lepidla nasadte ložisko kola na hřídel a dokončete montáž



Aplikace lepidla na hřídel

© SKF is a registered trademark of the SKF Group.

© SKF Group 2011

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use of the information contained herein.

