

SWAG 10 93 4573





Protect the engine compartment!

Bonnet insulation mats and lower engine compartment covers by SWAG

The low position of the engine compartment exposes it to damage from uneven road surfaces and is particularly vulnerable to speed bumps, road salts or accidents. Debris thrown up from the road can contribute to cracks and damage to the engine compartment cover.



2



Attention!

Torn or unsecured engine compartment covers are a safety risk and can become a danger to other road users if lost when driving.

The engine compartment cover is a safety critical component and, in addition to minimising noise, it ensures targeted cooling of the exhaust system (soot particulate filter) and engine compartment using the airflow. It also serves to protect the drive unit, the oil sump and the steering rod.

Fig. 1 Engine compartment cover with insulating properties for minimising noise, e.g., for VW Golf IV (SWAG no. 30 93 3543)

SWAG also supplies the insulation mat fixed directly under the bonnet to reduce engine noise and appropriate fixing rivets (e.g. SWAG no. 10 93 4573). The insulation mats are mainly damaged by rodents, fires in the engine compartment or accidents (see photo).

Fig. 2 Bonnet insulation mat, e.g. for MB E-Class (SWAG no. 10 93 3054)

For more technical information please visit: partsfinder.bilsteingroup.com